Each

: SPACER BUSHING

: D23273

: N/A

: HIA

: 9/21/2006

: C

: D2327 REV C

Date:

Thursday, 9/14/2006 1:08:16 PM

User:

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 28597

Estimate Number

: 10826

P.O. Number

This Issue

: NIA

: 9/14/2006 : NC

Prsht Rev. : N/A First Issue

: 28073

Previous Run

Written By

Checked & Approved By Comment

S.O. No. : NIA

: Est. F 05

Type

: MACHINED PARTS

Removed 303 SS KJ/EC

Additional Product

Job Number:



Seq. #:

2.0

3.0

Machine Or Operation:

Description:

M304R0375 1.0

Comment: Qty.:

0.1641 f(s)/Unit Inventory

Material: AISI 304 Round Bar Ø0.375"

(M304R0.375)

6.56461(s) Total:

304

304 SS ROUND BAR

Batch: H

1375X,065WALL

HARDINGE

Comment: HARDINGE CNC LATHE SMALL

Turn per Folio FA232 and Dwg D2327

Deburr

QC2

IS AS THEY COME OFF MACHINE

QC8 4.0

SECOND CHECK

00

Comment: SECOND CHECK 5.0 PACKAGING

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location: _<

06/10/12

Dart Ae	rospace	Lta							
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes	No) DQ	A: <u></u>	🛕 Date: 💇	6/10/12
					QA: N	/C Close	d:	_ Date: _	***
NCR:	-	V	VORK ORD	ER NON-CONFORMA	NCE (NCR	.)			
DATE	STEP	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
							1		

NOTE: Date & initial all entries

Date: User: Thursday, 9/14/2006 1:08:16 PM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SPACER BUSHING

Job Number: 28597

Part Number: D23273

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE







Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 2010,12

Dart Aerospace Ltd

Duitho	oopaoc	Lu								
W/O:			W	ORK ORDER CHAI	NGES					
DATE	STEP		PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCI	R: Yes I	No DQ	A:	Date:	
					QA: N/C Closed: Date:					· · · · · · · · · · · · · · · · · · ·
NCR:		W	ORK ORD	ER NON-CONFOR	MANCE	(NCR)			
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description					ation	Approval	Approval
		Section A	Chief Eng	Chief Eng) - 	Date	Secti	on C	Chief Eng	QC Inspector
			·	•						
				·						
						·				

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	28597		
Description: Spacer Bushing	Part Number:	D2327-3		
Inspection Dwg: D2327 Rev: C		Page 1 of 1		

		X First Ar	ticle	Prot	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	1	nments
Ø0.375	+0.005/-0.000	,373				MA+1 0.	D. is .373
Ø0.257	+0.005/-0.000	,259	V			M-7.1	
1.750	+/-0.010	1,752	V				
-							
							-
						·	
						di fi makanan	
easured by:	90	Audited by:	MS	P	rototype App	oroval:	N/A
Date: 6	06/10/11	Date:	aliolis			Date:	